



JON M. HUNTSMAN, JR.
Governor

GARY R. HERBERT
Lieutenant Governor

State of Utah
DEPARTMENT OF NATURAL RESOURCES
Division of Oil, Gas & Mining

MICHAEL R. STYLER
Executive Director

JOHN R. BAZA
Division Director

Inspection Report
Minerals Regulatory Program
July 2, 2009

Reviewed: TR

Mine Name: Goldstrike Mine	Permit Number: M/053/0005
Operator Name: USMX Utah, Inc.	Inspection Date: May 5, 2009
Inspector(s): Lynn Kunzler	Time: 9:30 am
Other Participants: Russell Shriener, BLM	Mine Status: Reclaimed

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls,	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Soils	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Revegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Purpose of Inspection:

Check recent installation of leach field.

Inspection Summary:

Dan Styler (under contract with the Division) recently notified the Division that the approved septic system and leach field has been installed and the area affected has been regraded. There was also an area where recent wildfire had damaged the collection pipe on near the reclaimed heap. This was also repaired and additional soil placed on top of the pipe to prevent damage in the future.

It appeared that the work completed was well done. The surface grading blended in with the adjacent areas. Disturbed areas will be seeded. The remainder of the reclaimed area still looks good. Vegetation is well established and does not appear to be affected by the recent wildfires.

Photos were taken to document site conditions and are in the file.

Conclusions and Recommendations:

Once vegetation has re-established on the disturbance created to install the septic system and leach field, this site should be closed.

Inspector's Signature _____

Cc: Russell Schreiner, BLM (Russell_Schreiner@blm.gov)

C:\Documents and Settings\OGMUSER\Desktop\2009 draft inspections\Insp-10292008-M0530005.doc